



Haryana PWD (B&R) Executive Engineer, Provincial Division No. 1, PWD B&R, Br. Kurukshetra. (136118) Email-ID <u>pwd-eepd1-kurukshetra@hry.nic.in</u> Phone No. 01744-239442

To,

The Principal, Wisdom World School, Kurukshetra

No. 877

Dated:- 29/03/2024

Subject:- Request for Building Safety Certificate of Wisdom World School, Kurukshetrą.

Reference:- Your office letter No. WWS/Building/2023-24/3882 Dated 29.03.2024.

In this connection, the above cited as subject building safety certificate is enclosed herewith for kind information and necessary action.

DA/Certificate

Executive Engineer

Endst. No.

Dated:-

Copy of above is forwarded to the Sub Divisional Engineer, Provincial Sub Division No. III, PWD B&R, Br. Pipli w.r.t his office No. Spl-1 dated 29.03.2024 for information.

DA/NIL

Executive Engineer

BUILDING SAFETY CERTIFICATE

It is certified that the existing building **WISDOM WORLD SCHOOL**, **SECTOR- 04**, **KURUKSHETRA** is having block(s) Floor(s) as per details below:

Details of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the	GROUND+4					
Block	FLOOR		~			

The building is owned/occupied by WISDOM WORLD SCHOOL have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of JAGDISH KUMAR (SDE, PWD B&R) on 29/03/2024 in the presence of SH. VINOD RAWAL, MANAGER, WISDOM WORLD SCHOOL, SECTOR- 04, KURUKSHETRA and that the building/premises is fit for occupancy for running school with effect from 01/04/2024 for a period of 1 (one years) in accordance with rule and subject to compliance of the specific conditions as appended.

1. Building of this school should be repaired every year.

2. Water should not be allowed to stagnate around and on the roof of the Building.

3. If Building is found cracked from anywhere, the same should be got vacated immediately and same should be got repaired immediately.

4. Institution will be responsible for safety of building from every angle and Fire-Fighting equipment should be in functional condition.

5. If the building of the school is to be extended, the same should be first approved form Structural Engineer.

6. Adequate Fire Safety may be adopted in the school campus.

7. Institute shall also ensure safety precautions from ceiling and vitrified tiles used in dado.

8. NOC may be considered as cancelled by this office if the college violates any of the above points.

Executive Engineer